

**VOLUNTEER SERVICE PROJECTS**  
2008  
**MURPHYS CHRISTIAN CAMP**  
www.murphyscamp.com  
For more information, contact:

Garry J. Moes, Camp Director  
209-728-3109 or 1-800-951-5353  
murphyscamp@hughes.net

**PROJECT #1 – ROOF REPAIRS**

Minor roof leaks at Managers' House need repair. Priority Level: 1. Cost: Unknown.

**PROJECT #2 – PAINTING UPPER LEVEL WIDEGREN CENTER LODGE**

Painting exterior siding to more closely match tan color of Dining Hall and Manager's House. Priority Level: 1. Cost Factor: Medium

**PROJECT #2 – HILLSIDE BEAUTIFICATION**

Landscaping design and construction for hillside on the right side of camp entrance driveway (site of current "Hidden Treasure Mine" sign). Priority Level: 3. Cost Factor: Low to Medium. Project underway.

**PROJECT #4 – HILLSIDE BEAUTIFICATION**

Landscaping design and construction for hillside in front of Lodge. Need drainage trenches. Priority Level: 2. Cost Factor: Low to Medium. Project underway.

**PROJECT #5 – MINIATURE GOLF COURSE**

Our miniature golf course area needs landscaping and golf course needs recarpeting. Materials on hand. Priority Level: 1. Cost Factor: Low.

**PROJECT #6 – PAINTING RAILS AND GARBAGE DOCK**

Repainting red hand rails and garbage dock around Dining Hall and stairs/railings at rear of Lodge. Priority Level: 1. Cost Factor: Low

**PROJECT #7 – OPERATIONS**

There is an ongoing need for volunteer help with house-keeping and cleaning of the Lodge following each camp session. Much raking needs to be done around the campus. Dining Hall floor needs periodic stripping and rewaxing. Kitchen helpers are always welcome, as well. Volunteers are also needed from time to time for "camp-sitting" during managers' absence or vacations. Priority Level: Varies. Cost: None.

**PROJECT #8 – ATHLETIC FIELD**

Athletic Field needs underground sprinkler system, topsoil and sod surface. Priority Level: 1. Cost Factor: High to Very High

**PROJECT #9 – INTERIOR LODGE PAINTING**

Lodging rooms, hallways and rest rooms need repainting. Materials available Priority Level: 2. Cost Factor: Low to Medium

**PROJECT #10 – TRAIL CONSTRUCTION AND MAINTENANCE**

Additional hiking trails need to be constructed throughout camp property. Construction guide available. Priority Level: 3. Cost Factor: Low. - Trail from play field to campfire area needs grading, ditching and graveling. Priority Level: 2. Cost Factor: Very Low to Low

**PROJECT #11 – TREE AND BRUSH REMOVAL**

Tree thinning and brush clearing is needed for fire prevention. Priority Level: 1. Cost: Low

**PROJECT #12 – BARN RENOVATION**

The barn at our former equestrian center needs painting and cleanup. Enclosing for recreational use is a possibility as well. Priority Level: 3. Cost Factor: Cleanup: None. Painting: Medium; Upgrading: High.

**PROJECT #13 – CAMP ENTRANCE BEAUTIFICATION**

Landscaping design and construction for camp entrance area, including hillside where camp sign stands and entrance area at fork in the entrance road, compatible with PG&E requirements around power pole. Include possible chain-saw sculpture. Priority Level: 2. Cost Factor: Low to High. Grant Funds Available.

**PROJECT #14 – INTERPRETIVE KIOSK**

Design and construction of interpretative kiosk in gold mine area, explaining history and geology of 49er Gold Rush era and the Mother Lode. Priority Level: 3. Cost Factor: Medium to High

**PROJECT #15 – OLD GENERATOR DISPOSAL**

An old industrial-size electric generator which has not been operated for many years needs to be removed from camp property. Priority Level: 1. Cost Factor: Low

**PROJECT #16 – DINING HALL DECK**

Dining Hall needs new decking surface. Overhang under deck and above apartment door needs renovation to stop leaking. Priority Level: 2. Cost Factor: High.

**PROJECT #17 – MAJOR CAPITAL CONSTRUCTION**

The camp's need for expansion includes the need to construct a new Dining Hall and Conference Center and renovation of the current meeting room into additional housing. Other housing addition possibilities include new family-style cabins. The camp needs a swimming pool to provide water sports activity currently available only off-site. Priority Level: 1. Cost Factor: Very High.